



INSTALL INSTRUCTIONS:

HOPPER

1. RIVET OR SCREW ITEMS -2 AND -3 TOGETHER (3 PL TOTAL). DO THIS TWO TIMES
2. RIVET OR SCREW ASSEMBLY TO ITEM -1 (NOTE RIVET DIRECTION)
3. PLACE ASSEMBLY ON TOP OF MILL, AND FASTEN WITH 1/4-20 SCREWS (4 TOTAL)

WITH EXTENSION

4. RIVET OR SCREW EXTENSION PLATE, ITEM -4 TO EXTENSION PLATE -5 (ITEM -5 TO BE ON OUTSIDE OF ASSY).

NOTE THAT THE ORIENTATION OF ITEM -4 MUST BE WITH THE LONGER EDGE ON TOP

5. REMOVE TOP HARDWARE FROM HOPPER ASSEMBLY, AND USE TO ATTACH TO EXTENSION ASSY THRU LOWER HOLES (4 PL)